









50K.
30K.

Audio on

Fassheller.

LID HINGE BASE SECURING SUPPORT POORLY
CONSTRUCTED.

(2) LID SECURING BOLTS SHOULD HAVE ~~BETTER~~ WASHERS?
CONTROL PANELS (4) SHOULD BE CHANGED TO LEXAN.

MONITOR:- FUSED ON BACK OF SET?

REMARKS:- Too much on display area OR LARGER SCREEN.
BALL TOO SMALL
MONITOR.

Checking Clicking

STATIC:-

A.C interruption no free games but on.
quick interruption display goes out of Vert Sync. ~~Power off for 10 sec~~ set sync on unit

STATE. CREDIT.	METAL TABLE RING	COIN MECH	CONTROLS.
✓ NONE	NO FUNCTION.	NO FUNCTION.	NO FUNCTION.
✓ 2 Player	NO FUNCTION.	NO FUNCTION.	NO FUNCTION.
✓ 4 Player	NO FUNCTION.	NO FUNCTION.	NO FUNCTION.